



*Figure 1: Wilcox Oil Company Superfund Site Tank 12 - southerly view of the cleared area that will be excavated. Dated 7/9/22.*





*Figure 2: Wilcox Oil Company Superfund Site Tank 12 - southerly view of the western berm with tank waste at surface. Dated 7/9/22.*





*Figure 3: Wilcox Oil Company Superfund Site, Lorraine Process Area southern view of ongoing tank waste excavation. Dated 7/9/22.*





*Figure 4: Wilcox Oil Company Superfund Site, Lorraine Process Area northern view of ongoing tank waste excavation. Dated 7/9/22.*





*Figure 5: Wilcox Oil Company Superfund Site, Lorraine Process area northern view of ongoing tank waste excavation. Dated 7/9/22.*





*Figure 6: Wilcox Oil Company Superfund Site, Lorraine Process area northern view of ongoing tank waste excavation. Dated 7/9/22.*



























